

JOB # 11-037
 JOB NAME: 6-25-11

QC POINTS HATCHER PASS

BASE #'S 6, 4, 3


PT	START/STOP	DESC.	H1
S24 SN 8543	11:48 / 1:18	FOREST POINT 15 // HUB (2) PHOTOS VIEW N/W	846 532 +622m 2579m
S25 SN 7225	12:00 / 1:26	FOREST POINT 16 // HUB (2) PHOTOS VIEW N/S	826 2518m
912 SN 0578	12:20 / 1:32	WETLANDS POINT 7 // HUB (2) PHOTOS VIEW N/E	535 1631m
913 SN 0331	12:30 / 1:36	WETLAND POINT 8 // HUB (2) PHOTOS VIEW NE/SE	509 1551m
BASE 32 SN 0578	3:17	BASE // SET HUB + TAC ON HATCHER PASS TURN OUT 20 MILES FROM WILLOW	442 SIDE ANT 0.943 w/ hook 0.956m w/ hook

6-25-11

TEMP 60° RAIN

LEICA 1200

J. HALL



NOTE: 600 SERIES ARE BRUSH POINTS
 0.8 MILES SEPARATION